

Lieutenant Governoi

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representative	es Present During the Inspection:
OGM	Karl Houskeeper

Inspection Report

Permit Number:	C0070035		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, October 07, 2010		
Start Date/Time:	10/7/2010 7:30:00 AM		
End Date/Time:	10/7/2010 11:00:00 AM		
Last Inspection:	Thursday, September 16, 2010		

Inspector: Karl Houskeeper,

Weather: Cloudy/Overcast, Temp. 54 Deg. F.

InspectionID Report Number: 2518

Types of Operations

✓ Reprocessing

Accepted by: jhelfric 10/7/2010

Permitee: SUNNYSIDE COGENERATION ASSOCIATES Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: SUNNYSIDE REFUSE & SLURRY

Address: PO BOX 159, SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	310.00
Total Disturbed	202.00
Phase I	5.50
Phase II	
Phase III	

Mineral Ownership

Fee

Other

Federal Underground Surface State Loadout County Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Richard Safley from Sunnyside Cogeneration was present during the inspection.

Insi	pector'	's Sia	nature:
	PO0101	~ ~ i ~	iiutui v.

Karl Houskeeper,

Inspector ID Number: 49

Date

Thursday, Octob

OIL, GAS & MINING

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Thursday, October 07, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		V	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches	✓		✓	
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		~	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Thursday, October 07, 2010

Page 3 of 3

2. Signs and Markers

The mine identification sign is located at the point of public access into the permit area

4.a Hydrologic Balance: Diversions

Several culvert inlets and outlets were observed that require maintenance following the recent storm events. The culverts lie at the base of the SPWF storage area and along the old coarse refuse haul road.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds all contain water from the recent storm events

6. Disposal of Excess Spoil, Fills, Benches

Excess spoil is now being hauled to excess spoil pile #1.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile appeared stable.